

PERSONAL SAFETY INFORMATION


Please make sure to follow the instructions from your guide at BHS-Sonthofen at all times and stay with them.

Safety rules

- In the production halls, please only use the paths marked in yellow. Protective clothing and footwear must be worn in work areas.
- Do not touch any components, sub-assemblies, or equipment.
- Do not enter areas marked accordingly if you wear electronic medical devices.
- In the event of an evacuation, make your way to one of the designated assembly points and report to the official in charge of evacuation so that they can determine that everyone is accounted for.
- The internal emergency service team can be reached by dialing ext. 222.



 Learn more

 www.bhs-sonthofen.com/ims



WELCOME TO BHS-SONTHOFEN

Thank you for visiting our facility. Special guidelines apply when you enter the plant grounds. In the interest of your safety as a visitor, you have been briefed on the guidelines. This also serves to protect against potential hazards and prevent disruptions to company operations.

Signing in and out

- Please sign in at the reception desk before entering the site and sign out when you leave.

General information

- Taking pictures and videos is forbidden anywhere on the site. This also applies to mobile telephones.



- Smoking is prohibited anywhere at the BHS-Sonthofen facility, except in designated smoking areas.



- Always use the designated exits and entrances when entering and leaving the building. Do not enter through the gates.

- Parking is permitted only in the reserved parking spots.

- The German road traffic regulations (StVO) apply throughout the entire site. Vehicles are only permitted to drive at walking pace.

Further instructions

- Further safety rules may be imposed in some cases. You will be briefed on these by the employee assigned to you when you visit.
- Work permits will be arranged in advance or by the responsible employee.

VISITING THE TEST CENTER

Personal protective equipment, including a safety vest, safety goggles, safety shoes and a helmet, are required in the testing facilities. When tests are being carried out, it may be necessary to wear additional protective equipment, which you will be assigned by an employee in advance.



Additional rules

- Do not enter closed-off areas during active operations.
- During active operations, entry to platforms and machines with safe access is prohibited except for instructed employees.
- Maintain a sufficient distance from moving parts.
- Fixed ladders may only be used by trained employees.
- Do not enter platforms and machines while major maintenance work is being performed.
- The equipment and hall crane may only be operated by employees.



BHS-SONTHOFEN SITE MAP

Our headquarters are located in Sonthofen, which is situated in the Allgäu region of southern Germany. The facility houses key divisions of the company (management, sales, development, and engineering). The majority of our products are produced at the Sonthofen facility. In addition, we manage our global activities and subsidiaries from here.

Key

- P1 Production (Mixing & Crushing Technology)
- P2 Production (Parts)
- P3 Production (Filtration Technology)
- P4 Production (Filtration Technology)
- T1 Test Center
- T2 Technical Center
- B1 Administrative Offices
- B2 Administrative Offices
- L1 Warehouse
- H1 Heating
- H2 Maintenance

